



GTEC UPS MODEL:

ZP120N


UPS USB Device-HID Test Program Setup

SERVICE DOCUMENT


UPS USB Device_HIDTestProgram

HIDTestProgram is kind of USB device testing tool and this tool will test that feedback information USB device whether is correct or not for engineer applying. Engineer can follow procedures for further operation.

- A. Ensure the UPS and PC connecting with USB cable.
- B. Double click “HIDTestProgram for USB Card V4.0.0.7.exe” to start USB testing tool.



- C. Select UPS model in the column marked “C”.
- D. Click “Open Device”
- E. “Find the HID Device OK” will be present in Log Information dialogue.
- F. Type Q1 in Add’/r’ column and then click ”Start Command”



If the USB device of the UPS is functional, the UPS’ response will show in Log Information dialogue. If there is no any response in Log Information dialogue, it means that communication is not success between PC and UPS. Hence the engineer should check UPS’ PCB.